



This adapter threads into your lathe's face plate so that you can add decorative carving details to a turned part, then return it to your lathe for further turning, without removing the face plate. The 5/8"-dia. post makes it easy to mount the adapter into the Veritas® Carver's Vise (or any other vise that takes a 5/8" shaft). The adapter is available in four thread sizes (1" × 8 tpi, 3/4" × 16 tpi, 1 1/4" × 8 tpi, and 33mm × 3.5mm).



**Figure 1: Face-plate adapter.**

**Installing the Adapter**

1. Thread the adapter into your lathe's face plate and lock it in place with a 1/2" wrench.



**Figure 2: Threading the adapter into a face plate.**

2. Loosen the clamp handle on the carver's vise and insert the adapter's post in the hole in the clamp shaft.



**Figure 3: Inserting the adapter into the carver's vise.**

---

**veritas<sup>®</sup> Tools Inc.**

814 Proctor Avenue      1090 Morrison Drive  
Ogdensburg, New York      Ottawa, Ontario  
13669-2205 USA      K2H 1C2 Canada

customerservice@veritastools.com  
[www.veritastools.com](http://www.veritastools.com)